Menlo Park Notebook #16 [N-79-01-21]

This notebook covers the period January 1879-March 1880. The entries are by Edison, Charles Batchelor, Francis Upton, John Kruesi, and Charles P. Edison. The name of Martin Force appears as a witness. All of the material relates to experiments on electric lighting and on the telephone. The electric light material includes notes and drawings of lamps; notes on filaments; notes, drawings, and calculations about generators; calculations relating to electric power distribution systems; notes by Batchelor on the cost and design of steam engines and boilers; and notes by Kruesi on the design of the central station for Menlo Park and the extension of the machine shop to house it. The telephone material includes notes and drawings by Batchelor and Charles Edison; notes by Batchelor on parts and prices for the telephone; and notes by Kruesi on making and packing the telephone receiver. The book contains 280 numbered pages.

Blank pages not filmed: 236-237.


Edison Laboratory Note Book No..10.

Pages 1 to 41.

...latinum & other metals, & metallic oxi..
...nts:


120 Broadway, New York.
, 189



266
266 265) 1.000 (.00377
795
2050
1855
1950

.00377 % lost in 20 minutes
in next 20 minutes
.00377
.01131
total .00377
.01578

60 minutes .00377
20 minutes .00754
.01518
80 .02272
.00754
.03026
100 .01131
.04157
120 .01131
.05288
140 .01131
.06419
.01131
.07550

266) 5.00 (300
798
2000

266) 17.00 (639
1596
1940
1798
2420

266) 17.00 (107
1862

.0266) 1000 (.00375 94
798
2020
1862
1580
1330
2500
2394
1060

37594
3
11278 2
X4 150375
X2 75188
225564

.0132

266
249
17

266) 2350 (84
2128
1220

266) 17.00 (6
1596
1040

Minutes	% loss during	Total
20	.003	.003
40	.01	.015
60	.007	.022
80	.007	.030
100	.011	.041
120	.011	.052
140	.011	.063
160		
240		.084
260		.084

210
157
53
36
18

157
121
103

Pipeclay Jan 21st 1919

Charles Estelle
Marion N Forney.

Mass piece of pipe clay
1.75 X .937
dried for 48 hours and then
measured
1.655 X 1.875
put in oven at 320° Fahr and baked for
2 hours then measured


Jan 23 1799
Pull Wicket
Look a piece

10 Fuses

1. 2 4 6
7 9 10 13
14, 15, 17, 19, 20, 22 1
23



Group 25 [illegible]
Appl

Scheelite Ca. groups
Fuels Ox H [illegible]

27 Dolomite fuses

~~Mag~~ ~~Magnesium~~ Magnesium groups

~~28 Magnesite~~ fuses
Ca
Perhnite

Mg Magnesium groups
29 Magnesite Infusible

31 Steatite Soapstone fuses
32 Talc fuses
33 Tremolite fuses
34 Pyrope fuses
35 Serpentine fuses

Ul. . Jany 23 1871 13

Tag

36 Corundum Adirondacks.

37 Disthene Fowler

38 Tschkik Mine

39 Kyanite Mine

40 Kaolinite Mine

41 Pyrophyllite Mine

42 Talcose Mine

43 Pargasite Mine

44. Hydrotalcite Sparkill



Min January 23 1879

5-1 Rhodonite Jas.

5-2 ~~Le~~

5-2 Green Iron fusible

5-3 Iron pyrites " "

5-4 Magnetic Iron " "

5-5 Hematite "

5-6 Limonite fusible

5-7 Spar Iron " "

5-8 " " Micaceous Impure

5-9



Jany 23 1879

Cy			Tag
66	Earthy Cl Ch		Franklin
Ni			
67	Copper Nickel		Franklin
68	Chathamite		
Bn			
69	Blende		"
Cd			
70	Blende	admixture	"
		Bisphuretted	
71	Zincite		Franklin
72	Calamine		"
73	Willemite		Franklin

Pt Jany 23 1879 Tats
74 Cerussite fuses with difficulty

75 ~~Pyrites~~ Phosphate fusible

76 Galena "

77 Molybdenite
fusible with difficulty fumes
a splendid light, does not
apparently fuse after many
min grind C.

78 Tin stone

79 Tin pyrites

144 0008
6
864

12
95

Bi

Jany 23 1879

80 Nat. Bismuth Tar
fusible, malleable after
fusion

81 Tellurit

82 Platinbalmine

Cu.

83 Cu fusible

84 " "

85 " "

86 Cu fusible "

87 Cuprum "

88 Argentu "

Jany 23 1879

89 Tin Lodes

90 Chyanvale tin ores

91 Cinnabar

combined with do

92 Mg.

93 Gold tin ores

94 Pt "

95 Molybdenite tin ores

96 do tin ores

97

98

99 B Tuesday January 23 1879 29
The Tunnels

10-0 Quartz

5 M.C. cold hot
" "

29 M.C. cold hot
" "

8 M.C. cold hot

11 M.C. Cold hot

12 M.C. Cold hot

25 Nc. Cold last night 23 1879 31

18 Nly. Jae

21 Nly.

22 Ny. in extremely small.

36 Ny.

82 Nc cold very little heated given off by the coals. For investigation.

80 Nly.

59 Chronic D[illegible] Jan 23 1879
slight C when cold better Feb 5
when Lot from carriage
stands a great heat

58. Ng [illegible]
conduction

57 Ng.

62 Ng.

74 Ng

D = 43° Jan 23 1879
42°5 Daily

46°5 to bring to
the same as No. 1 when
[illegible] vacuum

5-1°0



1,15) 2.74 (2.3
2 30
1 1 0

Reddish yellow with air
22°

Yellow in vac
23 1879
Tait

Dull red 17°

Volatilization 49° 1,15

Without 70° 2.74

2,74 1.15



38

10.5 in

~~.0001~~

3.141592

700

10.5
.07
.735

3.14159
.735
157079 5
942477
03

39

10.5 in

~~.03~~
.020

3.1415
.02
.06 2830
10.5

3.1415

.120

3.14
.12
.3768
~~.65~~ .65
1850

.65

1/4

222
.240 5

72 car

1/4 inches gave about 18 candles

~~60~~

70 candles per sq. in.

An explanation of the changes wh. occur in Pt. may be the following. The Pt absorbs an enormous amount of H gas which is given off at high temperatures

Feby 4 1879

T A E
Chief Instructor



3 Chalk
9 gr Acetate Liq.
1/2 Fluid oz Carbonic Soda.

Chalk for Effervescs.

New Remedies, 1871

Clive Balkwill

take 6 oz chalk in mortar and add to it 18 grains of tartaric Mucilage. grind the up fl dy then add 1 fluid oz Saturated Solution Carbonic Soda. when effervescence ceases well ground

.92 Ohms Feby 26 1879
Jack

20 feet .61 Ohms

5 ft to turn

5 | .61
.122 Ohms in 1 turn
25 turns
610
305
2 | 5.125

4 | .61
.152 Ohms in 1 turn
25
760
304
2 | 3.800 Ohms
1.900 Ohms

.018
.018
144
18
.000324

1.9

6 4 8 | 125
4
24
24
0

125 00
62

26
26
156
52
676

120

.025
.028

.624

60.5 | 1256 2.06
1210
4000

50

8 × 12
3 × 12
144 ft
on track

.01	5 ft
.02	10 ft
.02	10 ft
.05	25 ft
.10	50 ft
.20	100 ft
.12	60 ft
.65	250 ft
1.10	

10 lbs of #15 wire
2 lbs of #18 wire
1 lb of #23 wire

52

53

.01	5 ft	No. 15	
.02	10 ft		
.02	10 ft		10 lbs
.05	25 ft		
.10	50 ft		
.10	50 ft		
.20	100 ft		
.50	165 ft	No. 18	2 lbs
1.00	No 20		10 lbs
1.00	No 118		
2.00	No 23		1 lb.
5.00	No 27		1 lb.
10.00	No 30		1 lb.
10.00			2 lbs.
20.00			

10 lbs No 15
2 lbs No 18
1 lb No 23
1 lb No 27
2 lbs No 30



L.L.V. Sewell.

Feby 26 1879

c/Mch 5th 1879 Tec'g

A.W.S. patent is to be taken out in the
for U.S. and which I furnish you
a model. I also furnish you a
second model to go with the
Canadian patent.

This is the C.W.S. specification.

The scope of patentee's invention
is to transmit and receive
sounds telegraphically at a distance
with great power and exactness
loss of volume.

~~The principle of the~~
~~The invention consists~~

The peculiar action upon which ~~the invention~~ the invention is based was patented by me (original Electromagnetic) ~~of~~ Number ~~—~~, An application of the action to telephony was also patented ~~applied for~~ (1878) This is the patent where a band of paper was used) — The present application consists more particularly in devices which make the invention perfectly practicable for use in Commercial and infinitely more reliable & effective



A is a cylinder of ~~el. H~~ Compressed Chalk soaked in an Electrolyte the Solution such as a Common alkali Hot Urinary Excrement or Conductor of Electricity

I will mention that any finely
divided non conducting material
or porous body having capillary
pores (which has no chemical action
upon the absorbed solution
may be used -

This cylinder is secured to a
shaft B ~~and~~ & the cylinder is
by the operator by means of
rotated ~~by~~ the toothed
wheels c d, and
shaft & handle e f
or worm & pinion or may be
with pinion of a
particularized and, the
~~of the~~
Clock work or analagous
motor made to replace

the Hand of the operator.

Resting upon the cylinder A is a flat spring g connected to the disc plunger D. this spring is pressed upon the check with a pressure of several pounds by means of the wire K & spring h. the screw M serving to increase or decrease the amount of pressure - The line wire XX is connected to the spring g while the Earth wire is connected

to the shaft on which the
Cylinder A is secured.
Now the cylinder C
rotated in the direction
shown by the arrow 2 no
Current passes the normal
friction of the spring g
upon the surface of the
Cylinder A will be very
great and the spring
will be carried forward
in the direction of the
rotation of the cylinder
thus pushing inwardly

68.

69.

4 5/16 - 14.

34.



The diaphragm D. if now a current passes whose direction is such that Hydrogen will be produced upon the surface of the ~~Piece~~ piece g in contact with the Chalk. the friction will be reduced to an Extent proportional to the strength of the current ~~and the~~ since the diaphragm will regain its natural position and continue there as long

as the current passes as the friction between the spring a & A is too small to produce sufficient traction ~~[illegible]~~ if now the current ceases the normal friction at once obtains. The traction increases & the diaphragm is instantly pulled outwardly if now a current in the opposite direction is transmitted the effect is ~~[illegible]~~ scarcely noticeable as the evolution of

Oxygen in the surface of the spring q. does not except with a ~~few~~ few ~~to~~ saturations decrease the friction like Hydrogen but on the contrary q. gas tends to increase the normal friction, hence I allow a constant current to circulate in the line and am thus enabled to ~~use~~ utilize the opposite wave by causing them to weaken the constant

Current which is always
in a direction to evolve
Hydrogen on the surface
of the spinning J.
for instance if the constant
Current was upon the line
the only ~~one of the~~ waves
in one direction would
produce an effect
whereas if a constant current
is circulating one of
the waves" added to that
~~Strength~~ of the current

and the other wave
neutralizes or nearly neutralizes
the Constant Current
hence the tendency of
1 wave is to produce a
lessening of fraction of
say 5 units which is
to that produced by
the Constant Current
say 5 together give
10 units if now an
opposite Current is
sent it neutralizes
the Constant Current

we have the normal
friction of the cylinder
whereas if no Constant
Current was used one
Current would lessen the
friction by 5 units & the
opposite Current would
perform no work.

N is a receptacle
Containing water.
resting in the water
is a roller R composed
of any flexible absorbent
substance such as

Sponge or felt,
The lever to which the
roller is attached by,
which the roller may
be brought in contact
with the cylinder A.
Extend through the box
to the outside, the
object of this device
is to supply the cylinder
with a water heat by
Evaporation & made of
a Conductor to the
Electric Current

In practice when all the
apparatus is enclosed in a
Cast iron case the loss
in evaporation is very small
and if the roller be held
against the cylinder =
if the cylinder be raised
three or four times the
Clock work takes up
sufficient motion so that
it will perform its functions
for a week or more without
again winding it =



The Connections are as follows

Tr is the Receiver Circuit Telephone
transmitter placed in a
local circuit with the
induction Coil Ic with

local battery of the operation
of the switch lever upon
the button n. then the current
proceeds from the Local
battery X X via wire 1
to the [illegible] in the ordinary
coil thence via wire 2 to
3 thence to the switch lever
thence via wire 4 through
the Carbon transmitter thence
by wire 5 to the post
6. thence to the battery
The sonorous waves of the
Voice are translated into
Electric waves of a precisely
analogous character

in the second day Cont of the
Induction I. in the
well known manner;
The Commotion of the mare
here is to follow the line
from the distant station
Enters at the point d.
thence via. w.n.w. 9 to the
Pole thence via w.n.w. 10 to
the Key Corner thence
via. w.n.w. 6. to the point
p ~~th~~ of the worlds
thence via w.n.w. 4 to
the spring 9 of the
Meridian thence thro'

the main chalk to wm
8, to 4 through the
secondary call thence
via wm 3 to the Switch
from which it will be remarked
by mi ii thence via wm 4
through the Communication to
wm 5- thence to post
6 & thence via wm 12
to the post e which is
Connected to the earth.
I will mention that either
of the posts d e may be
Connected to the ground
or line, It will be remarked
that the main line runs
through the Communication

which is communicated to the
Lead Cutting hence a
portion of the Current leaks
into the main line & it
is this portion which then
leaks into the line that
serves as a Constant
Current for short lines
but if the line be to
long or has too great a
resistance the small
leakage Current is
so weakened as to be
insufficient to produce
a loosening of friction

between the spring 9 & the
Chalk Lever 9 ~~subsidy~~ 1
or more cells ~~in~~ in the
main line =
~~Switch~~ ~~board~~ ~~is~~ ~~in~~ ~~this~~ ~~position~~ ~~(1st)~~ ~~the~~ ~~lever~~ ~~in~~ ~~Central~~ ~~with~~ ~~a~~ ~~transmitting~~ ~~&~~ ~~receiving~~ ~~can~~ ~~go~~ ~~on~~ ~~simultaneously~~ ~~by~~ ~~turning~~ ~~the~~ ~~switch~~ ~~lever~~ ~~to~~ ~~the~~ ~~point~~ ~~p~~.
The ~~Telephones~~ apparatus
is disconnected & the
Call Bell apparatus

become operative, the line
enters at the post d
passes through the bell via
wire 9. thence via 10 to
Key. thence via 6. to p.
thence via lever to wire 3.
thence via 2 through the
primary coil 4 via 1 to
local battery through chest
to post 6 thence via 12
to post c to earth, by
depressing the key the
circuit is opened & closed
& the two local batteries
at each end of the

line Galvanic operation &
using the Bell.

Inillumentum, that the two receivers herein described & the two transmitters may all be connected in one fixed & operated without the aid of undulatory Coils but the receivers are not equal but at from the use of the Coils, also that the Receivers will act as transmitters by reason of the fact that when the opening of Chalk as at rest the resistance of the whole

is generally about 2500
ohms & this resistance is
reduced momentarily to
2 or 300 ohms by the slight
movement of setting the
Chalk or the spring ~~the~~
~~sheet~~ hence the movement
of the diaphragm D by the
voice produces the same
result or nearly so as the
Carbon transmitter, and
advantage ~~~~ of course
is to be taken of this fact
the surface of the
spring g. should be adjusted
to increase the effect
and an induction coil
having a primary coil







with an Electrolyte — a solution
with a ~~n~~ Electrode Connected
to a diaphragm plate or other
body Capable of rendering
the motion produced by Electricity
~~en~~ audible —

3rd In combination with
a ~~n~~ solid expanded [illegible]
in a closed receptacle [illegible]
of a ~~n~~ material [illegible]
a equipment for supply of
water out as [illegible]

4











14
20
28











6 — 18·84

5'

5 turns wants equal ·25 ℔ Hour ·80

12=50 inch

11





New shell for Order 58

18 wire in 25 coils

18 wire = ·049 = 232·3 feet per chain

Per 6" chain = 18·85 -

~~[illegible]~~

18 wire & silk = ·055 = 343 wires in circumf

18·85 − 2·(·40 for diameter) = 16·85

16·85 ÷ ·055 = 306 wires

306 wires ÷ 25 = 12 wires to each coil : 6 on top and 6 on bottom or 6 whole turns

6 whole turns would be 27 inch × 6 = 162 × 3 layer = 486 inch = 40·5 feet = ·17 ohms

Resistance 8 ring = $\frac{(12 \times \cdot 17) \times (13 \times \cdot 17)}{(12 \times \cdot 17) + (13 + \cdot 17)} = \frac{2 \cdot 04 \times 221}{2 \cdot 04 + 2 \cdot 21}$

$\frac{4 \cdot 5064}{4 \cdot 25}$ = about 1 ohm



Wire for Field magnets of Order 58

Coil 2 feet long = 4 feet long of 4" diameter

Resist. required 1 ohm

1 layer of No 16 cotton Cov. = 72.34 inch = 6.13 feet
= 1½ ohm (wire not dia)

1 layer of No 18 cot cov = (11 turns per inch) = 48 inch
× 11 = 528 turns of 12.56 inch each =
528 × 12.56 = 6631 inch = 552 feet = 1.1 ohm

2 layers @ 13 = (9 per inch) 9 per inch
4 × 9 = 432 turns × 12.56 inch =
5.50 m = 450 feet + 1st layer 450 feet =
= 900 feet = 1.01 ohm

Order for this (37 feet per lb)
3 lbs of No 13 cotton Cov.
wire the diameter of this
wire bare must be .095
95 thousandth





90

The long magnets require 643 ft
of No 11 = .120 wire each =
0.461 Ohm = 56 lbs.


126
127

Plan No. 1

Plan of Lot No. 1 in Block No. 1 of Subdivision of Block No. 1 of Subdivision of Block No. 1 of Subdivision of

130

131

B

D 1/4

B

D. W. Patchin

Gramme



April 4 1879
T W K

April 4 1879
T W K
Gramme Machine



April 4 '874

Tea

Robertson



136

April 4
1879

137

April 2 1879



138

105

139



B
B
B
B
Stelle
Mühle
Mühle
Mühle
Mühle

142

143

Chaussiette

144



Section of Fuse

April 7/1877

145



T. W. E.
Ultra-practicable





148

149

Regulators of S.A. No 2 Order No 112

Charging Selector



TNR



9 april, 1879 151

TAE



7.6 Gravitation

April 3
14:52

60 mins 60 s = 14,52

HP
1000

250 machines 1 hr

50
50
2500
37

15

45

750
45-
375-0
300
12) 3375-0 (2812
24
97
96
15-
12
30
24

2812.

520.

30

Paula

Rec R

1	—	1·74	
2	—	1·11	
3	—	1·04	
4	—	·96	
5	—	·86	
6	—	·74	
7	—	·61	
8	—	·45	
9	—	·41	
10	—	·41	
11	—	·41	
12	—	·45	
13	—	·66	
14	—	·72	
15	—	·84	
16	—	·93	
17	—	1·02	
18	—	1·04	
19	—	1·13	
20	—	1·17	
21	—	1·16	
22	—	1·19	
23	—	1·16	
24	—	1·12	
25	—	1·07	
26	—	1·00	
27	—	·92	
28	—	·85	
29	—	·78	
30	—	·74	
31	—	·74	
32	—	·78	
33	—	·84	
34	—	·91	
35	—	·97	
36	—	1·01	
37	—	1·04	
38	—	1·04	
39	—	1·04	
40	—	1·04	

May 9 1879







May 9 1879

May 9 1849





166



850,

300 | 50000 D
166,666
20
333,320

300,

167



168

169


Yuma 120
120
Gila 100
480
300 1000
30 8 St.
60 8 S.F. 180
480 Yuma 120
Tucs 120
18000 480
1896 1080.
8
Sonora


170
113
2000
226,000
12 = 113.
2000
226,000
171
76,54
2000

172

20 1/2

1	100
2	50
4	25
8	12½

12½

25, 50

173

20.5.82 12

1

25.

Dollars	Lights
132 00	110
119 90	110
107 80	110
95 70	110
83 60	110
71 50	110
59 40	
47 30	
35 20	
23 10	
11 00	
786 50	

110 wires

to 340 feet from station

1100.

2350
7150
9500

132 00
119 90
251 90

36

37
18 ½
55

55
25
275
110
1375
2
27.50. ¼ mile

10

7

110
10
1100

$\frac{1}{4}$ miles 12 $\frac{1}{2}$ wire, 10 lights each Lamp

1250	1500
1240	1490
1230	1480
1220	1470
1210	1460
1200	1450
1190	1440
1180	1430
1170	1420
1160	1410
1150	1400,
23200	
1140	1390
1130	1380
1120	1370
1110	1360
1100	1350
1090	1340
1080	1330
1070	1320
1060	1310
1050	1300
1040	1290
11990	
1030	1280
1020	1270
1010	1260
1000	1250
990	1240
980	1230
970	1220
960	1210
950	1200
940	1190
930	1180
10740	

110 Lights

132,850

110 Lights

119,190

107.80



189
95
284 $-\frac{1}{4}$ ohm

1 cent per foot

.10 .10

Last span 10 150 ft Lamps labled R 10 to the cond. A 125
78 180. at 2.5c 12.50

27 127

780
780
8580

156, 20,
5
781

920	1170
910	1160
900	1150
890	1140
880	1130
870	1120
860	1110
850	1100
840	1090
830	1080
820	1070
9570	

9570

810	1060
800	1050
790	1040
780	1030
770	1020
760	1010
750	1000
740	990
730	980
720	970
710	960
8360	

8360

700	950
690	940
680	930
670	920
660	910
650	900
640	890
630	880
620	870
610	860
600	850
7150	

7150

590	840
580	830
570	820
560	810
550	800
540	790
530	780
520	770
510	760
500	750
490	740
5940	

7150
1210
5760

70

540
to 2310
440

70
70
180
110,

5
500
to
440

440
to
340.

740
to
640 = 4750

2710
1210
1500

5750
2100
4750

640
to
540 = 3520

4750
1210
3540

3520
1210
2310

George

Nov 17th 1879

Take a large [illegible]
[illegible] Carbon [illegible]
Powder the coke about
size of pea [illegible]
put up about 4 cells thus

Take a [illegible]
time dust coke
using a solution of Caustic

[illegible]

Do the [illegible]
from paraffin


LINE
EARTH
G

184

~~Armature Speed of~~
~~Steam Engine~~ 105
~~Belt~~

Edison Dynamo
First 25-0
Second Speed 65-6½
Third " 20

Edison Dynamo 

185

Fall in E. M. F.
1 lamp 100 Ohms
Conductor 1 Ohm Machine ½ Ohm

~~1.5 100~~ ~~100~~
.1.5 101.5
5-0

.50 25
51.5 26.5

12.5
14

186

1 — 100 / 101.5

2 — 50 / 51.5

3 — 25 / 26.5 — 33.33 / 34.83

4 — 25 / 26.5

5 — 20 / 21.5

2.00624		
2.0064		
1.9936	.985	
2		
1.9872	.971	985²
2		
1.9744	.942	
1.6996		
1.7118		
1.9872	.971	
1.9744	.943	971²
1.9488	.889	
1.5228		
1.5420		
1.9808	.957	
1.9616	.915	957²
1.9232	.838	
1.3979		
1.4232		
1.9744	.943	
1.9494	.890	943²
1.8788	.792	
1.3010		
1.3324		
1.9686	.930	
1.9372	.869	930²
1.8788	.756	

6 — 16.66 / 18.16

7 — 14.28 / 15.78

8 — 12.5 / 14.

9 — 11.11 / 12.61

10 — 10 / 11.5

1.2206		
1.2588		
1.9628	.918	
1.9256	.843	
1.8512	.694	
1.1547		
1.1982		
1.9565	.905	
1.9138	.818	
1.8260	.670	
1.0969		
1.1761		
1.9508	.893	
1.9016	.797	
1.8032	.635	
1.0454		
1.1008		
1.9446	.880	
1.8892	.775	
1.7784	.600	
1.		
1.1607		
1.9393	.870	
1.8786	.756	
1.7572	.572	

11 [illegible]
7.09
10.59

.9586
.0248
1.9338 .859
1.8676 .721
1.7352 .543

12 [illegible]
8.335
9.839

.9208
.9927
1.8281 .847
1.8562 .718
1.7124 .516

13 [illegible]
1.6923
9.1923

.8861
.9635
1.9226 .837
1.8452 .700
1.6904 .491

14 [illegible]
1.14
8.64

.8537
.9365
1.9172 .826
1.8347 .683
1.6688 .466

15 [illegible]
6.66
8.16

.8237
.9120
1.9117 .816
1.8234 .666
1.6468 .443

16 [illegible]
6.25
7.75

.7959
.8893
1.9066 .806
1.8132 .650
1.6264 .423

17 [illegible]
5.8823
7.3823

.7696
[illegible]
.8683
[illegible]
1.9016 .797
1.8032 .636
1.6064 .404

18 [illegible]
5.585
7.055

.7447
.8485
1.8962 .787
1.7924 .620
1.5848 .384

19 [illegible]
5.263
6.763

.7213
.8301
1.8912 .778
1.7824 .606
1.5648 .367

20 [illegible]
5
6.5

.6990
.8129
1.8801 .769
1.7722 .592
1.5444 .350

25

4.
5.5

.727
.529
.280

.6021
.7404
1.8617
1.7234
1.4468

30

3.333
4.833

.690
.476
.226

.5228
.6442
1.8386
1.6772
1.3544

15) 2000 (133
15
50
45
5-0

15.4323

.30

3.3010
1.1884
2.1126

192

100 Ohm lamp 1 Ohm conductor in machine

100/107 = 21

		2.0043
	.990	T.9957
.982	.980	T.9914
	.961	T.9828

2 50/51 = 1.6990

		1.7076
	.980	T.9914
	.961	T.9828
	.924	T.9656

3 33.33/34.33 = 1.5228

		1.5307
	.971	T.9871
	.942	T.9742
.941	.886	T.9484

193

4 25/26 = 1.3979

		1.4150
	.961	T.9829
.954	.924	T.9658
	.854	T.9316

5 20/21 = 1.3010

		1.3222
	.952	T.9788
.907	.907	T.9576
	.823	T.9152

6 16.66/17.66 = 1.2216

		1.2471
	.993	T.9745
	.889	T.9490
	.791	T.8980

7

14.28 / 15.28 = 1.1547

.937 · 1.1831 = T.9716

.877 · 1.9432 = T.8864

.770 · T.8864

8

12.5 / 13.5 = 1.0969

.926 · 1.1307 = T.9666

.857 · T.8572 = T.9332

.735 · T.8664

9

11.11 / 12.11 = 1.0454

.917 · 1.0432 = T.9622

.840 · T.9244

.706 · T.8488

10

10 / 11 = 1.

.909 · 1.0414 = T.9586

.826 · .830 · T.9192

.689 · T.8384

11

9.09 / 10.09 = 0.9586

.901 · 1.0641 = T.9545

.811 · T.9090

.653 · T.8160

12

8.3333 / ~~5.8823~~ / ~~2.4503~~ / 9.3333 = .8928

.890 · .9702 = T.9496

.795 · .793 · T.8992

.629 · T.7984

13 7.6923 / 8.6823 = .8861

.885 × .9392 = T.9469

.783 × T.89388 = T.7876

14 7.14 / 8.14 = .8537

.877 × .9106 = T.9431

.769 × T.8862 = T.7724

15 6.66 / 7.66 = .8237

.870 × .8842 = T.9395

.757 × T.8790 = T.7580

16 6.725 / 7.25 = .7459

.862 × .8603 = T.9356

.743 × T.8712 = T.7424

.743 × .552

17 5.8823 / 6.8823 = .7696

.855 × .8377 = T.9319

.731 × T.8638 = T.7276

.534

18 5.555 / 6.555 = .7447

.848 × .8163 = T.9282

.718 × T.8564 = T.7128

.516

19

5.263 .7213
6.263 .7968
.840 T.9245
.706 T.8490
.499 T.6980

20 5. .6990
6. .7782
.833 T.9208
.694 T.8916
.482 T.6832

25 4 .6021
5 .6990
.800 T.9031
.640 .640 T.8062
.410 T.6124

30 3.333 .5228
4.333 .6268
.769 T.8866
.575 .592 T.7720
.350 T.5440

592
2
1184

592

$$\mathcal{H} = \frac{\mathcal{E}^2}{R} \qquad R = r + \frac{l}{n}$$

Work in lamp =

$$\mathcal{E}_l = \frac{\mathcal{E}\,\frac{l}{n}}{r + \frac{l}{n}}$$

$$W_l = \frac{\mathcal{E}^2 \frac{l^2}{n^2} \frac{l}{n}}{\left(r + \frac{l}{n}\right) \times \frac{l}{n}} = \frac{\mathcal{E}^2 \frac{l}{n}}{r + \frac{l}{n}} \div$$

$$\frac{\mathcal{E}^2 \left(\frac{l}{n}\right)^2 \frac{1}{l}}{\left(r + \frac{l}{n}\right)^2} \qquad W \frac{\mathcal{E}^2 \left(\frac{l}{n}\right)^2}{\left(r + \frac{l}{n}\right)^2} \frac{1}{l}$$

200 965
903,5

3.9845
3.9557
1.0288

1.06

1.775
8225

1.2492
.9157
.3341

2.16 Ohms

2455
7545

.3901
.8660
.5241

334





Portland Portland Portland Portland Portland Portland Portland

Sanft Hal. Folk. G.

52½ 30 2
48 10
22 190 R
55 174 R
50 24

Solarium
Protinum
Cherok Lacinium
Marcinium
Prosium Dinarium
Protinum 16,
Machine Dinarium
Machine 12
Machine Phorinum
Machine 1 84.
81 19



50 : 50 :: 10 : X

$X = \frac{500}{50} = 10$



767 : 233 :: 10 : X

$X = \frac{2330}{767}$

500

$\frac{1}{7.5} \div \frac{1}{10} = \frac{1}{75}$

$\frac{1}{15} \times \frac{1}{75} = \frac{1}{1075}$



$\frac{1}{7.5}$ $\frac{1}{75}$ div in Amount

$\frac{1}{15}$ current in circ

$\frac{1}{15} \times \frac{1}{75}$ $\frac{1}{1075}$

$\begin{array}{r} 75 \\ 325 \\ 75 \\ \hline 1075 \end{array}$



$\frac{1}{8}$ $\frac{1}{80}$

$\frac{1}{8} \times \frac{1}{80} = \frac{1}{640}$



~~10~~ Ohms total

$\frac{1}{100}$

$\frac{2}{10} * \frac{1}{5}$

$\frac{1}{500}$



$\frac{1}{15}$ $\frac{1}{150}$

$\frac{4X2}{15} = \frac{8}{150}$

8) 150 (281

1 0

$\frac{1}{281}$

214

5 Ohms

10 Ohms



120 Ohms Total

$\frac{1}{120}$

$\frac{5}{12} \times \frac{1}{120} = \frac{5}{1440}$

$\frac{1}{190} = \frac{1}{248}$

~~$\frac{1}{14} \times \frac{1}{10} \quad \frac{1}{121.8}$~~

215

$\frac{1}{10}$

4 Ohms

$\frac{1}{110}$

$\frac{4}{110} \times \frac{1}{110} = \frac{4}{12.10} = \frac{1}{302}$

~~10~~ 6 Ohms

$\frac{1}{13}$

$\frac{1}{13}$

$\frac{1}{13} \times \frac{1}{130}$

1 — 1/80

1/8 = Current

1/64 of Else in Coil

1/64 X 1/80 = 1/5120

80
5120

2 Ohms

2/81 X 1/90 = 2/7290 = 1/3645

7/2/9 — 1/90

90

3 Ohms

1/64 X 3/100 X 1/10000 = 3/10000000 = 1/3333333

10 — 1/100

4 Ohms

4/121 X 1/110

7/4/110 — 1/5324

11
4
121
110
1210
121
4 | 13310
3326

5 Ohms 1/120 — 1/12

5

744
120
2880
144
5 | 17280
3456

3456

218

6 Ohms

$\frac{1}{130}$

$\frac{6}{169} \times \frac{1}{130}$

$\frac{7}{6}$
$\frac{13}{13}$
$\frac{13}{39}$
$\frac{13}{169}$

$\frac{1}{3661}$

130 | 1.0000 (0.00769
1000
910
900
780
1200
1170
30

169 | 6.0000 (0.0355
507
930
845
850
845
5

$\frac{1}{2}$ Ohm

$\frac{1}{7.5}$

7.5
7.5
375
52.5
56.25

$\frac{1}{75} \times \frac{1}{7.5} \times \frac{1}{75}$

112.5
75
5625
7875
8437.5

75 | 1.0000 (0.0133
75
250
225
250
225
25

7.5 | 1.0000 (0.133
75
250
225
250
225
25

1 Ohm = 1
2 Ohm = 333 1/3 = 2 1/333
3 Ohm = 249 7/11 = 3 1/42
4 Ohm = 801.5 = 4 1/2
5 Ohm = 1836 = 5 1/21
6 Ohm

748 1/2

249) 400 (1
249
151

2) 249
124 2
1

249) 400 (1
249
151

2) 249
124 2
1

141) 700 (4
564
136

21) 29 (1
21
8

332) 140 (0
0
140

2) 332 (166
2
13
12
12
0

2) 166 (83
16
6
6
0

83

676) 3244 (4.8 6370

2604

636

5 ohms Total

716.5) 2863.00 (4

2868

139.5) 5570.0 (39.9

5571.0

399.5) 12500 (.03

1197.0

45100

716) 22440 (31

2148

692

399.5) 12500 (.03

1197.0

51.50

716) 69200 (.09

6444

5560

5370

190

716) 2863.00 (4

2864

24

716) 69200 (96.62

6444

4760

4296

4640

4296

344

399.5) 600.50 (1.5

399.5

201.00

199.5

01.50

one ohm combination

1 500 : 500 :: 1 : ? = 1 ohm

2 333 : 666 :: 1 : ? = 2.003

3 249 : 751 :: 1 : ? = 3.016

4 199.5 : 801.5 :: 1 : ? = 4.019

5 164 : 836 :: 1 : ? = 5.097

6 139.5 : 860.5 :: 1 : ? = 6.169

five ohm combination

4 716 : 284 :: 10 : ? = 3.96

10 500 : 500 :: 10 : ? = 10

15 399.5 : 600 :: 10 : ? = 15.03

20 332 : 668 :: 10 : ? = 20.12

25 284 : 716 :: 10 : ? = 25.21

1 911.5 : 89.5 :: [illegible] = .981

2 836.04 = 1.96

3 772 : 228 :: [illegible] = 2.95

284) 7160 (25
568
1480
1420
284) 6000 (.214
568
320

9115) 89.500 (.981+
82035
7465 0
7292 0
173 00
91 15

836) 1680 (2
836

836) 1640 (1.96
8040
7524
5160
5016
144

772) 2280 (2.95
1544
7360
6948
4120
3860
260

716) 2840 (3
2148
692
644
48

716) 3030 (4
2864
166

716) 2840 (3.96
2148
6920
6444
476

7100
142
2856
7144

(714.4)
300
786
244

876
924

95
914

974 : 26 :: 10 : ?

260
260

260 | 10
974) 260000 (.26
194 8
6520
5844
676
52

2 | 26 | 13
100 | 50

2832 4

2920
2124
796

~~3775~~

708 : 292 :: 10 : ?

708) 2920 (3

703) 2920 (4



Sept 11 1879.

Saint Louis
Electric Light

Chas Batchelor

Edison Laboratory Note Book No. 13.

Pages 227 & 228.

See Edison Patents:
214,636
214,637
218,800
227,027
227,028
227,029

Sept 11 1879. 22

Sand stone
Electric light





Telephone parts

1 Wooden base
2 " box
3 " box Cover
4 Rubber Receiver box
5 " " cover
6 " " back.
7 Receiver bridge
8 " Palladium Spring
9 " " " nut
10 " " washer
11 " " washer connection
12 Receiver adjusting screws 4
13 " " " pin
14 " " rubber
15 " Brass chalk barrel
16 " " " washer
17 " " " nut
18 " Mica diaphragm 18 thou 20 d
19 " Connection strip 00
20 " Straps

21 Arm
22 Shaft guard
23 Worm wheel and shaft
24 Movable bearing
25 Worm bracket
26 Worm,
27 Handle (Brass
28 Handle (Composition)
29 Worm guard (dirt)
30 Arm bracket
31 Arm joint washer
32 Shaft sleeve
33 Bracket pin
34 Paper washer on joint
35 Coil spool
36 Coil winding
37 Bell
38 6 Bindposts
39 2 Keys with backpoints
40 2 front front points
41 2 Brackets with backpoints
42 2 Key buttons

43 hinge springs (2)
44 2 connection for cover
45 Transmitter base
46 " cover
47 Boxwood ring
48 " " connec. Strip
49 Bottom platina screw
50 Glass disc
51 top platina disc
52 Diaphragm with bush
53 Diaphragm Screw
54 Rubber bush
55 " Screws
56 1 Joint Screw
57 Rubber tube for Receiver connection
58 " connection wire
59 10 Copper washers
60 Coil Core
61 Bushings for Receiver 17/32 & 5/8 Ebonite.

18

Transmitter	$1.35
Bell	1.05
Receiver	3.25
Balance Box, Cord, etc.	4.00
	9.65
	1.25
	10.90
~~1.25~~	
	$12.15

Mr Jurnist Chalk roller
and palladium 12.15 / 28 / 12.43

~~Shipping~~ Packing the 28 cts per
~~telephone~~.

Then $13.00 - 20 = 12.80
Then $13.00

2898

Transmitter

Oct 1st 89.

1 To turne Drill & tap both castings the faces of both must be perfectly true. the Diameter of face Diaphragm to be 2 1/4 inch exact. Casting must be smoothed on both & lay flat on box, Depth must be same as our first piece.

2. To make box wood ring

3. " " & platinize & Brass screws

4. " which will be furnished in the rough for you make " " " the top plate &

" " make & put in glass disk

5 " make concaction plate & Concactions

6 " Assemble after Japaning Diaphragme with screws & heads Vagues " if not japanned on both sides.

7 rubber bushs

8 To solder & blue the screws & Vagues them To put it on the box for 75¢.

Receiver

1 To make the shaft rollers complete
The screws washers & nuts are furnished
as blank punchings
rollers to be turned to size exact
platin'd & drilled & taped & hence
japanned

Extra rollers for 25 d.

2. The Diaphragme to be cut & drilled
& put in case

3. To make the spring complete
to size exact, the Palladium
to be put on so that it does not need
any filing not to be wetted
with any fluid, highly polished
without emery, finished straight
& exact to size.

4. To make connections with # 3 d6
35 wires

5 To make the rubber piece to
size & shape same as model

6 To put spring on Diaphragme & set
it correct.

for 60 d dirty



Fig. 5 inch wheel grooved the armature runs the sewing machine motor





Sizes of Packing boxes for Telephones

Oct 21st 99.

small

6½ × 12 × 8 deep.

large

17 × 55½ × 12½ deep.

all inside measure.

18 Drill
3
16 "


Londerous



1/4 mile 8in Water pipe
Cast Iron and Laying
$2500 rough.
pipe 1575 00
Laying 925 00
2500 00

1200 HP
Condensing Eng. & Pumps
~~Invested~~ Leaving Interest
Non condensing plant
in $50 000 in Engines

$1600 less invested in
Boilers

1/3 less water for Boiler

252

253

1/3 less room for Boarders

1/3 less depreciation on boilers

Saving in Journal #1460 per year

Saving in cost

per Contra

Extra Cost of Coal &c over Non Cond. #1460.00

Depreciation Acct

Cost of piping, wells etc
for Condensing water (Wasted)

Saving in Boiler water
by using Condensing water
over and over $\frac{2}{3}$ (Surface Condenser)

For 1200 H.P. Boilers we should
want 8000 feet of Condensing
surface

We Copper pipe for $\frac{1}{32}$ thick $\frac{5}{8}$ hole
takes 32000 feet long @ 1280#
for ends = 1 33280#
= 12380 lbs at 38¢
= $4704.41

Cost of Condensing Engine
per hour per H.P. at 2½ lbs
~~Coal .918~~
~~Water .03~~

Coal	.31
Labour	.13
Oil Waste	.016
Rent	.11
Labour doubling	.13
	.122
Water	.05
Interest	.17
Depreciation	.01
	.948 cts

Jam

1

4

Cylinder 14 X 24

$\frac{14}{42}$ Repair diameter

$\frac{56}{196}$

$\frac{1}{6}$ stroke average pressure 31 lbs.

Pressure 6076 lbs. piston speed

500 ft per min = 42 H.P.

4 Cylinders = 288 H.P.



Cylinder 14×24 contains 3696 □ inch. 3696×2 = 7392. Then 7392 ÷ 1728 = 4.27 cu ft of steam at 1.8 atmospheres. 4.27 × 1.8 = 7.28 cu ft at pressure atmosphere for each revolution. Then 7.28 × 125 = 910 cu ft per minute

910 ÷ 28 = 32.5 lbs water per min. 32.5 ÷ 10 = 3.25 lbs coal per min — 3.25 × 60 = 195 lbs coal per hour

195 × 4 = 780 lbs per hour

250 H P at 3.25 = 812 lbs ℔. Coal per hour



March 3 1880



One Station 1250 H.P. 180 Revs
5 - 250 H.P. Engines - to design of Fig. 15 ?
1880

Belts - 1 @ 7000
Shafting & pulleys 5500
Iron Structure - 8 000
Woodlagging - 3 000
5 Engines 12 500
5 Engine Foundations 2 500
40 Forges &c. Machines 36 000
Boilers 25 000
Heating & Cooling 7 000
Steampipes
Chimney 1 000
Building

Page
21 Gr. widths
96 - Smiths
33 - Machine
15 - Boilers
165 - Engines

1250 I.H.P.
3 lbs. Coal per I.H.P. per hour for 10 hours
37500 = 17 tons average per day.
100 tons at 35 cubft = 3500 cub ft should be stored in bunkers.
Make 6 bunkers 8 ft wide 5 ft. deep
6' x 8' = 54 sq ft Chimney — 5 to 50 sq ft ...
7 1/8" Square outside. —
7" (Internal 6 sq") Steampipe for about 250 ...
6" " (32 sq") " " 300 ft ...
5" " " Total 1250 ...

30 lbs Water per hour per lbs ... advanced standard.
1250 H.P.
30 lbs water per 10 hours
375.000 lbs Water consumed per day.
46 800 gallons
Pump capacity 4700 gall per hour ...
place 2 Pumps to 400 ft 3" 100 gallons each ...
and 2 " " 200 " " 800 " " ...


B & M. Boiler Plant.
Coal bunkers
Front
Chimney
Boilers
Coal bunkers
Boilers
Coal bunkers
Front
Boilers
Coal bunkers
Boilers
Coal bunkers
Front
Boilers
Coal bunkers
Boilers
Coal bunkers
Front

Boilers for Kelly Water Works Station
Made there

80 H.P 66" diam 16 ft long 69-4" tubes
3½" × 42" Dome – (then $912.00).–

7" diam. (40 Sq ins) Steampipe for each 250 H.P Engine –
6½" " (32 sq ins) " " " 200 H.P
6 × 32 = 192 = 15½" ins diam for all 5 Engines

350 Plant: of 3 H.W. but 9 instead of 8 rows of tubes, add – 6" to height –
Plan for Albert from other Plant. –

Chimney 8 ft Sq in clear. –
14 ft. Sq. outside
18'-11" outside of Brickbench –
88" each batt. 17" width of Walls.
6"x4" wide buckstay at middle
9"x6" wide Coal posts
36" diam of drums – about 18' long –

Smoke flues each 36"×30"–

21" pitt. below floor.
9'-11" height of Brickwall at front end
11'-6" to centre line of drum & Water line
13'-6" to top of columns & bottom of 36 12" Supporting Beams.
18'-5" – centre to centre of bearing beams
29" front of wall to centre of 12" Support
15" front wall to front 24" Bridge –
7'-6" to Mud drum on 12" Support
3'-2 to end wall – 12" ins wall –
42" c. to c. of Mud drums. –

p. 40

Mathiesbrop extension - Bill of Timber

25	Floorbeams	3" x 18"	22'-6"	long pine
23	Roofbeams	2" x 12"	24'—	"
2	Sills	4" x 16"	23'—	yellow pine
4	—	— " —	27'—	" "
1	"	— 4" x 12"	27'—	" "
4	Stringers	— 6" x 6"	26'—	" "
5	Trusses	— 8" x 12"	23'—	" "
10	"	8" x 8"	12'—	" "
9	Posts	— 10" x 12"	15'-6"	" "
5	"	— " —	12'-6"	" "
9	Braces	— 4" x 8"	6'—	" "
4	"	— 4" x 6"	4'—	" "
10	Uprights	— 4" x 6"	12'—	white pine
2	—	2 x 6	12'—	
2	—	4 x 6	15'—	
2	—	"	14'-6"	
4	—	"	13'—	
2	—	"	13'—	
2	—	2½" x 6"	13'—	
4	—	"	12'—	
6	—	"	15'—	
6	—	"	15'-6"	
8	—	2" x 6"	4'—	

Roofing 600 sq. ft. of 1" [illegible] 5.21
600 " " 1½ pine
Roofboard 700 " " 1" board seam.
Flooring 701 800 x
Siding - for 700 sq. ft.
Trimming 12 wide
5 Windows
2 Doors
Partitions
10 Loads Bonham 6.00
10 Barrels cement
Brickwork
70 ft. x 15½ x
60 ft. x 1' x
8500 bricks
9000 bricks

Machine Shop extension —

26'9" — 3½" Shafting with 5 Hangers 30"

26'9" — 2½" " " 5 " 20"

20 Pulleys — 6" face 32" diam.

1 Pulley — 25" " 36" "

1 " — 17" " 36" "

1 " — 26" " 60" " for 3½" Engine

1 Shaft 3½" — for Exchange

2 or 3 Hangers 3½" — 30" drops

Belts.

20 — 5" — 25' long 15 long

1 — 12" — 24' —

1 — 24" — 24' —

1 — 24 — 27' —

Total Estimate

Wood Resist. Shafting Pulley $2800

Caloric Experiment.

8" area = 50.265

area × 6½ stroke = 314 cub. in. per stroke = 1 revol. — water piston 3½ stroke

16" 2¾ = 376
8" 1¾ = 47½
8" 2¾ = 198
620 inch long pipe 4" Diameter forms.

Condenser Engine three places

Pistn 16" diam = 201.06 × 10 = 2010.6 sq. inch
4 7/8 area = 471
2480 ÷ 5 sq. inch heating surface

6 of 8" diam = 25.13 × 10 = 251.3
8" area = 50.265
301.565 sq. inch heating surface

contents from above
5/8 heating surface 1963 × 625 = 1227.5 sq. inch heating surface

Heat transmits the surface for heating and evaporizing at 212 degree — compared with Cast Iron Stove heating.

Air and all other Gases & Gases have same expansion, that is 1/491 = .002037 times of their bulk for every degree of heat. — (Specific gravity compared with water = .00120196) that is they expand from 32° to 212° = from 1000 to 1376

8" area = 50.265 × 3½ = 176 Cubic inch the cyl contains

By equal pressure Steam has 3.136 times the specific heat of Air — and at equal volumes 1.965 times

20 Volumes of Water absorb 1 volume of air

Anthracite one ℔. requires 195.45 cub. ft. air
Bituminous " " 150.35 " "
Coke " " 108 " "
Wood " " 90 " "

1250 ℔. P. × 3.8 = 4750 ℔. per hour.
or about 63 ℔. per min. requires
63 × 200 of air = 12600 cubic ft per min.

№ 10 Sturtevant Blower = 1000 revolutions per min.
= 1/15 350 = 600 revol. per min. 60" Diam. of Blast
14" Diam of pulley 12 face 10 Centre of Bearings
24" Diam of inlet — 18" × 24" Square of outlet.

9.76 Horsepower.

10 H.P. Vertical Engine 4½ Cylinder 8" stroke. 36" Diam of Flywheel 12" face
300 ℔. weight 200 revol. per min. 16" 32 Diam
room 69½" high — room 9 ft. to ceiling = 315 ft.

1 ℔. of Coal requires 9 ℔. of air
= 1250 × 9 = 11250 cubic ft. = 187 cubic ft. per min.
25 to 30 ℔s of Water per hour

Locomotive Boiler 12 to 14 Cyl 8" stroke 16" D

Cubic — continued

7⅞ area = 48.7 × 11½ "steele" = 560
+ 2½ " fall 5 × 7/8 = = 3¾
8 area = 50.265 − 11.78 × 5/8 = = 7¼
− 7 area = 38.484
6" area = 28.27 × 175 − 178 = = 20½
Content in Chamber = 590 cub inch

Pipes...
16 × 21 3/4 long = 348."
8 × 23 " long = 184"
4 × 10½ " long = 42"
= 574 ins. Length of pipe

5/8" cubic diam of pipes = .3067 × 574" = 176 cub inch
5/8" inside diam " " = displaced by pipes

590 −
176
414 cubic ins. content for air in Chamber

314 cb. ins. content displaced in 6% per steele

5/8" area = 1.963" × 574" length of pipe = 1126 3/4 sq inch heating surface of pipes =

Erickson's heating Rat offers 990 square inch inside surface to the acre or about 1/4 of 3 square pipe surface.

6" area = 50.265 = 50 cyl. Gasser Cubic —
7½ " = 38.484 = 38 cyl. replacement 10 cubic
= 88.749 = 88 cyl.
12

8 Wood fillings = 60 cub ins.
16 " = 85 "
8 " = 15 "
1 " = 4½ " 20%
4 " = 5 "
1 × = 1 1/16
1 × = 1/16

displaced by Wire 213 cubic ins.
Cubic = 20%

414 174 cubic ins. 42%
240 88
174 31% cyl. [illegible]
[illegible] 120 cyl.

6" area = 50.265 Cyl. [illegible]
× 4.5 " [illegible] = [illegible]

226 414 [illegible] 120 = 3 [illegible]
174 88
52 26% [illegible]
314
88
226

March 16 1880.

Temperature of Room 17° C.
Exhaust air at slow speed - 67° C.
" " " fast " - 69° C.

Exhaust Steam varying from 98 to 102° C.
apparently not affected during work of Air engine

Pressure in Air engine 10" Mercy of Vacuum 15"
even while Exhaust heat operated best by hand
slow motion was given to revol - -

With smallest addition of Steam 42 revol per
62° Temperature of exhaust steam.
Add Steam 60 revol - 65° - " "
" " 75 " - 68° - " "

March 17th.

Air & Steam 30 revol with Condenser of
very small condensation in cyl.
" " 50 " Without " only
very marked condensation in cyl.
" " 52 " with Condenser of Steam
very small condensation in cyl.
" " 32 " Without " only